

		Jan/Feb	Feb/Mar	Mar/Apr	Apr/Jun	Jul/Aug
Orlingbury Road						
Average Speed						
	Inbound	25 mph	26 mph	27 mph	26 mph	27 mph
	Outbound	29 mph	30 mph	30 mph	31 mph	33 mph
85th Percentile						
	Inbound	30 mph	30 mph	31 mph	30 mph	32 mph
	Outbound	34 mph	34 mph	35 mph	35 mph	38 mph
% Vehicles Speeding						
	Inbound	13%	15%	18%	15%	21%
	Outbound	36%	41%	44%	44%	60%
Hardwick Road						
Average Speed						
	Inbound			30 mph	27 mph	27 mph
	Outbound				34 mph	34 mph
85th Percentile						
	Inbound			38 mph	32 mph	32 mph
	Outbound				40 mph	40 mph
% Vehicles Speeding						
	Inbound				20%	23%
	Outbound				66%	66%
Wellingborough Road						
Average Speed						
	Inbound				24 mph	25 mph
	Outbound				29 mph	29 mph
85th Percentile						
	Inbound				30 mph	30 mph
	Outbound				34 mph	34 mph
% Vehicles Speeding						
	Inbound				15%	15%
	Outbound				37%	37%
Hilltop						
Average Speed						
	Inbound	31 mph		39 mph	39 mph	38 mph
	Outbound		35 mph		38 mph	41 mph
85th Percentile						
	Inbound	43 mph		46 mph	46 mph	46 mph
	Outbound		46 mph		46 mph	48 mph

- There has been an uplift in both speed and the percentage of drivers speeding on Orlingbury Road. However, this will have been caused from the sign being moved to a position closer to the village boundary.
- A small increase in the percentage of drivers speeding coming into the village on Hardwick road, but no change in average speeds. The new signs have reduced inbound average speed by 3mph and 85th percentile speed dropping 6mph
- Little change in behaviour on both Wellingborough Road and Hilltop. However, Outbound traffic on Hilltop has seen a 2mph increase in average speeds. Maximum speed recorded was 100mph at 23.30 on 2nd July.

Confirmation required at OCM: Does the community speed watch do both inbound and outbound on Hilltop?